








典型特性曲线

Typical Characteristics Curves



可靠性试验

Reliability Test Items and Conditions







焊接指导 (1)

Guideline for Soldering

1. 使用烙铁手工焊接

Hand Soldering

2. 使用焊台





1. 贮存:

Storage

