

目录

Catalogue

电性参数
Electrical Characteristics.....3

典型特性曲线
Typical Characteristic Curves.....5

可靠性实验
Reliability Test Items And Conditions.....6

外形尺寸
Outline Dimensions.....7

包装
Packaging.....8

焊接指导
Guideline for Soldering.....10

使用注意事项
Precautions.....12

电性参

-25 Absolute Maximum Rating($t_a=25$)

Parameter	Symbol	Value	Unit
Max Power Dissipation	PD	50	mW
Max Continuous Forward Current	IF	20	







r

r







焊接指导 (1)

Guideline for Soldering

1. 使用烙铁手工焊接

Hand Soldering

30

2. 回流焊接

Reflow Soldering:







