














包装 (1)


Packaging (1)

载带与圆盘尺寸



:

1. (mm)
1. Size unit is mm (mm).
2. $\pm 0.1\text{mm}$
2. The dimensional tolerance is $\pm 0.1\text{mm}$.





焊接指导 (1)

Guideline for Solder

使用烙铁手工焊接




30 W

300

3

LED

Manual welding is recommended only for repair and heavy industry situations. A soldering iron of less than 30W is recommended to be used in Hand Soldering. Please keep the temperature of the soldering iron under 300 while soldering. Each terminal of the LED is to go for less



PE V

B3

B

19

118


MANROX





使用注意事项（2）

Precautions (2)



In designing a circuit, the current through each LED must not exceed the absolute maximum rating specified

