







可靠性试验

Reliability Test Items And Conditions

Continuous Operation Test	IF=150mA Ta=25 × 1000hrs
	IF=150mA Tj=140 × 1000hrs
Low Temperature Storage Test	-40 × 1000 hours
High Temperature Storage Test	100 × 1000 hours
Moisture-proof Test	85 , 85 %RH for 500 hours
Thermal Shock Test	-40 × 30 minutes—100 × 30 minutes, 100 cycle



生效标准

- * U S .
- * U defines the upper limit of the specified characteristics. S defines the initial value.
- * 2 24 .
- * Measurement shall be taken between 2 hours and 24 hours, and the test pieces should be return to the normal ambient conditions after the completion of each test.



包装 (1)


Packaging (1)



:

1. (mm)
1. Size unit is mm (mm).
2. ±0.1mm
2. The dimensional tolerance is ± 0.1mm.


圆盘及载带卷出方向及空穴规格 Disk and carrier belt direction of roll and hole dimensions




包装 (2)

Packaging (2)


◇ 防潮抗静电包装 Moisture Proof and Anti-Static Foil Bag



◇ 外包装箱 Cardboard Box



◇ 标签说明 Label Expansion







(" i v x v o ố

